

Docket No. 59479.21601
Customer No. 30734



09/115764

PATENT

CoJC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: RE39,327 E

) Confirmation No.: 1754

)

Inventor: Michael REASONER

) Group Art Unit: 3682

)

Reissue Date: October 10, 2006

) Examiner: Vinh Luong

)

For: CONDUIT SHORTENING ADJUSTMENT ASSEMBLY

REQUEST FOR CERTIFICATE OF CORRECTION

*Certificate
OCT 20 2006
of Correction*

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

ATTENTION: CERTIFICATE OF CORRECTION BRANCH

Sir:

Pursuant to 35 U.S.C. § 254 and 37 C.F.R. § 1.322, this is a request for the issuance of a Certificate of Correction in the above-identified patent. Two (2) copies of PTO Form 1050 are appended.

The mistakes identified in the appended Form occurred through no fault of the Inventor, therefore, no fee is due in conjunction with this submission. Issuance of the Certificate of Correction containing the corrections is respectfully requested.

Respectfully submitted,

BAKER & HOSTETLER LLP

P. Alan Larson
Registration No. 53,184

Date:

10/18/06

Washington Square, Suite 1100
1050 Connecticut Avenue, N.W.
Washington, D.C. 20036
Phone: (202) 861-1500
Fax: (202) 861-1783

OCT 20 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : US RE39,327 E
REISSUED PATENT DATED : October 10, 2006
INVENTOR : Michael REASONER

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7

Line 22, after "second", please insert --conduit--;

Line 24, please replace "ajustment" with --adjustment--.

MAILING ADDRESS OF SENDER:

Baker & Hostetler LLP
Washington Square, Suite 1100
1050 Connecticut Avenue, N.W.
Washington, D.C. 20036

PATENT NO. US RE39,327 E

No. of additional copies

Page 1

→ 1

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

OCT 20 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : US RE39,327 E
REISSUED PATENT DATED : October 10, 2006
INVENTOR : Michael REASONER

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7

Line 22, after "second", please insert --conduit--;

Line 24, please replace "ajustment" with --adjustment--.

MAILING ADDRESS OF SENDER:

Baker & Hostetler LLP
Washington Square, Suite 1100
1050 Connecticut Avenue, N.W.
Washington, D.C. 20036

PATENT NO. US RE39,327 E

No. of additional copies

Page 1

→ 1

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

OCT. 20 2006